

- Deviation from RSDO Catalog Impacts Cost and Schedule
- Original 5 Second to Internet Requirement is High Risk
 - Change to 7 Seconds Should be Reasonable
- 1 ms C&DH Processing Requirement Breaks
 Vendors Design \$,\$\$\$,\$\$.\$\$
- On-Board Bus Architecture can Improve Response Time


Response Time Constraints




BASELINE GLAST C&DH



TIMELINE



LAT and GBM on HIGH RATE BUS



DIRECT CONNECT GBM to LAT